




STEP
1



STEP
2



STEP
3



* ASK YOUR AEP SPAN REPRESENTATIVE ABOUT FACTORY NOTCHING.



SPANSEAM



EAVE HEM

SPS-06